



Canadian Automobile Sport Clubs – Ontario Region Stewards' Race Event Report

Event Name	Toronto Autosport Club			Location of fire/rescue vehicle(s)	Pit Out
Event Dates	Jan 24 - 25, 2026	Organizing Club	TAC	# of fire/rescue vehicle interventions	
Location		CASC Permit	IR01		
Event Stewards	Bob Stiver			# of ALS ambulance hospital transports	
Chief Steward	Bob Stiver				

Summary of Penalties

Car	Accused	Reg.	Infringement	Penalty	Comments	Clerks
58	Rebecca Freugel	2.1.19	cracked windshield	Verbal warning	See comments	
20	Trestan Cabal-Periera	7.0	Aggressive driving, not l leaving room	Verbal Warning	Attached RFA	
141	Daniel Birel	7.0	Aggressive driving, not l leaving room	Verbal Warning	Attached RFA	

Comments

58 - Rebecca Foegele, Toyota cracked windshield. Driver was told last year to have the windshield repaired. Driver agreed to have it repaired before the next/DAC event or the car would not be allowed on track.

Recommendation: Rule 2.1.11 regarding placement of ballast should be reviewed. There was a car with ballast (2 x barbell weights) bolted on the top of the hood. It was noted that in a incident the weights could become detached, becoming a danger. Suggest that ballast should not be attached on the surface of a body panel.

Scrutineering Report Attached