


# Fire Extinguisher Explosion on DZ 28

Friday Nightshift 7<sup>th</sup> May 2010

D Crew






# Actual Bracket Involved

Arrows point to bolt location





**Fatigue cracking**

**Third extinguisher showing wear from bracket strap rubbing**

Alternate bracket design showing adequate gap between bolt heads and extinguisher

